

Company		Mine
ERC Mining Indiana Group		Gold Star Mine
Inspection Date:	Monday, January 7, 2019	
Areas Inspected:	Surface Areas of Underground - pit, highwall, roadways, openings, pumps, belts, shop, office, substation	
Findings / Law(s) Violated:	47.41	
Corrective Actions Taken:	Hazards have been addressed with management and corrected	
Recommendation(s):	Check labeling on chemical containers when used and replace or correct if needed.	
Inspection Date:	Monday, February 4, 2019	
Areas Inspected:	Surface Areas of Underground - pit, highwall, roadways, openings, pumps, belts, shop, office, substation	
Findings / Law(s) Violated:	No Violations noted.	
Corrective Actions Taken:	None	
Recommendation(s):	None noted	
Inspection Date:	Tuesday, February 26, 2019	
Areas Inspected:	Surface Areas of Underground - pit, highwall, roadways, openings, pumps, belts, shop, office, substation	
Findings / Law(s) Violated:	No Violations noted.	
Corrective Actions Taken:	None	
Recommendation(s):	None noted	
Inspection Date:	Tuesday, March 12, 2019	
Areas Inspected:	Surface Areas of Underground - pit, highwall, roadways, openings, pumps, belts, shop, office, substation	
Findings / Law(s) Violated:	47.41	
Corrective Actions Taken:	Hazards have been addressed with management and corrected	
Recommendation(s):	Check labeling on chemical containers when used and replace or correct if needed.	
Inspection Date:	Friday, March 22, 2019	
Areas Inspected:	Surface Areas of Underground - pit, highwall, roadways, openings, pumps, belts, shop, office, substation	
Findings / Law(s) Violated:	No Violations noted.	
Corrective Actions Taken:	None	
Recommendation(s):	None noted	
Inspection Date:	Thursday, March 28, 2019	
Areas Inspected:	Surface Areas of Underground - pit, highwall, roadways, openings, pumps, belts, shop, office, substation	
Findings / Law(s) Violated:	No Violations noted.	

Corrective Actions Taken:	None
Recommendation(s):	None noted

Company		Mine
Gibson County Coal		Gibson Mine (North)
Inspection Date:	Monday, January 28, 2019	
Areas Inspected:	Surface of Underground Areas - roadways, pumps, shop, office, substation, fuel storage areas	
Findings / Law(s) Violated:	No Violations noted.	
Corrective Actions Taken:	None	
Recommendation(s):	None noted	
Inspection Date:	Wednesday, February 13, 2019	
Areas Inspected:	Surface of Underground Areas - roadways, pumps, shop, office, substation, fuel storage areas	
Findings / Law(s) Violated:	No Violations noted.	
Corrective Actions Taken:	None	
Recommendation(s):	None noted	
Inspection Date:	Thursday, March 7, 2019	
Areas Inspected:	Underground Areas (Portal 2) - primaries, secondaries, belts, unit	
Findings / Law(s) Violated:	47.41	
Corrective Actions Taken:	Hazards have been addressed with management and corrected	
Recommendation(s):	None noted	
Inspection Date:	Wednesday, March 13, 2019	
Areas Inspected:	Surface of Underground Areas - roadways, pumps, shop, office, substation, fuel storage areas	
Findings / Law(s) Violated:	No Violations noted.	
Corrective Actions Taken:	None	
Recommendation(s):	None noted	

Company		Mine
Gibson County Coal		Gibson South Mine
Inspection Date:	Wednesday, January 9, 2019	
Areas Inspected:	Underground Areas - primaries, secondaries, belts, unit	
Findings / Law(s) Violated:	47.41	
Corrective Actions Taken:	Hazards have been addressed with management and corrected	

Recommendation(s):	None noted
Inspection Date:	Thursday, February 14, 2019
Areas Inspected:	Underground Areas - primaries, secondaries, belts, unit
Findings / Law(s) Violated:	47.41
Corrective Actions Taken:	Hazards have been addressed with management and corrected
Recommendation(s):	None noted

Company	Mine
---------	------

Peabody Midwest Mining	Francisco Mine
-------------------------------	-----------------------

Inspection Date:	Monday, January 14, 2019
Areas Inspected:	Surface Areas of Underground - roadways, pumps, belts, shop, office, substation, pit
Findings / Law(s) Violated:	No Violations noted.
Corrective Actions Taken:	None
Recommendation(s):	None noted

Inspection Date:	Wednesday, January 23, 2019
Areas Inspected:	Underground Areas - primaries, secondaries, belts, unit
Findings / Law(s) Violated:	75.1714-7(c); 47.41; 75.202
Corrective Actions Taken:	Hazards have been addressed with management and corrected
Recommendation(s):	None noted

Inspection Date:	Friday, March 1, 2019
Areas Inspected:	Underground Areas - primaries, secondaries, belts, unit
Findings / Law(s) Violated:	75.1714-7(c)
Corrective Actions Taken:	Hazards have been addressed with management and corrected
Recommendation(s):	None noted

Inspection Date:	Wednesday, March 6, 2019
Areas Inspected:	Underground Areas - primaries, secondaries, belts, unit
Findings / Law(s) Violated:	47.44(b)
Corrective Actions Taken:	Hazards have been addressed with management and corrected
Recommendation(s):	None noted

Company	Mine
---------	------

Sunrise Coal		Carlisle Mine
Inspection Date:	Thursday, January 10, 2019	
Areas Inspected:	Underground Areas - unit, secondaries, primaries, belts	
Findings / Law(s) Violated:	75.202	
Corrective Actions Taken:	Hazards have been addressed with management and corrected	
Recommendation(s):	None noted	

Inspection Date:	Tuesday, January 15, 2019	
Areas Inspected:	Surface Areas of Underground - office, shop, warehouse, fuel storage areas, parts yard, belts	
Findings / Law(s) Violated:	No Violations noted.	
Corrective Actions Taken:	None	
Recommendation(s):	None noted	

Inspection Date:	Wednesday, February 27, 2019	
Areas Inspected:	Surface Areas of Underground - office, shop, warehouse, fuel storage areas, parts yard, belts	
Findings / Law(s) Violated:	No Violations noted.	
Corrective Actions Taken:	None	
Recommendation(s):	None noted	

Inspection Date:	Thursday, March 14, 2019	
Areas Inspected:	Surface Areas of Underground - office, shop, warehouse, fuel storage areas, parts yard, belts	
Findings / Law(s) Violated:	No Violations noted.	
Corrective Actions Taken:	None	
Recommendation(s):	None noted	

Company		Mine
Sunrise Coal		Oaktown Fuels #1 Mine
Inspection Date:	Wednesday, January 16, 2019	
Areas Inspected:	Underground Areas (Portal 2) - unit, secondaries, primaries, belts	
Findings / Law(s) Violated:	75.360(f); 75.400	
Corrective Actions Taken:	Hazards have been addressed with management and corrected	
Recommendation(s):	None noted	
Inspection Date:	Monday, March 4, 2019	
Areas Inspected:	Surface Areas of Underground - office, shop, warehouse, fuel storage areas, parts yard, belts	

Findings / Law(s) Violated:	No Violations noted.
Corrective Actions Taken:	None
Recommendation(s):	None noted

Company	Mine
----------------	-------------

Sunrise Coal	Oaktown Fuels #2 Mine
---------------------	------------------------------

Inspection Date:	Wednesday, January 30, 2019
------------------	------------------------------------

Areas Inspected:	Underground Areas - unit, secondaries, primaries, belts
------------------	--

Findings / Law(s) Violated:	75.606, 75.512
-----------------------------	-----------------------

Corrective Actions Taken:	Hazards have been addressed with management and corrected
---------------------------	--

Recommendation(s):	None noted
--------------------	-------------------

Inspection Date:	Wednesday, February 6, 2019
------------------	------------------------------------

Areas Inspected:	Underground Areas - unit, secondaries, primaries, belts
------------------	--

Findings / Law(s) Violated:	No Violations noted.
-----------------------------	-----------------------------

Corrective Actions Taken:	None
---------------------------	-------------

Recommendation(s):	None noted
--------------------	-------------------

Inspection Date:	Monday, February 18, 2019
------------------	----------------------------------

Areas Inspected:	Underground Areas - unit, secondaries, primaries, belts
------------------	--

Findings / Law(s) Violated:	75.606
-----------------------------	---------------

Corrective Actions Taken:	Hazards have been addressed with management and corrected
---------------------------	--

Recommendation(s):	None noted
--------------------	-------------------

Inspection Date:	Tuesday, February 19, 2019
------------------	-----------------------------------

Areas Inspected:	Underground Areas - unit, secondaries, primaries, belts
------------------	--

Findings / Law(s) Violated:	75.202
-----------------------------	---------------

Corrective Actions Taken:	Hazards have been addressed with management and corrected
---------------------------	--

Recommendation(s):	None noted
--------------------	-------------------

Company	Mine
----------------	-------------

Triad Mining	Freelandville West Mine
---------------------	--------------------------------

Inspection Date:	Tuesday, January 8, 2019
------------------	---------------------------------

Areas Inspected:	Surface Areas of Underground - office, shop, warehouse, fuel storage areas, parts yard
------------------	---

Findings / Law(s) Violated:	No Violations noted.
-----------------------------	-----------------------------

Corrective Actions Taken:	None
Recommendation(s):	None noted

Inspection Date:	Tuesday, January 22, 2019
Areas Inspected:	Surface Areas of Underground - office, shop, warehouse, fuel storage areas, parts yard
Findings / Law(s) Violated:	No Violations noted.
Corrective Actions Taken:	None
Recommendation(s):	None noted

Inspection Date:	Tuesday, February 5, 2019
Areas Inspected:	Surface Areas of Underground - office, shop, warehouse, fuel storage areas, parts yard
Findings / Law(s) Violated:	No Violations noted.
Corrective Actions Taken:	None
Recommendation(s):	None noted

Inspection Date:	Thursday, February 28, 2019
Areas Inspected:	Surface Areas of Underground - office, shop, warehouse, fuel storage areas, parts yard
Findings / Law(s) Violated:	No Violations noted.
Corrective Actions Taken:	None
Recommendation(s):	None noted

Inspection Date:	Friday, March 8, 2019
Areas Inspected:	Surface Areas of Underground - office, shop, warehouse, fuel storage areas, parts yard
Findings / Law(s) Violated:	77.1110; 77.1110
Corrective Actions Taken:	Hazards have been addressed with management and corrected
Recommendation(s):	None noted

Inspection Date:	Wednesday, March 27, 2019
Areas Inspected:	Surface Areas of Underground - office, shop, warehouse, fuel storage areas, parts yard
Findings / Law(s) Violated:	77.1110
Corrective Actions Taken:	Hazards have been addressed with management and corrected
Recommendation(s):	None noted

Triad Mining		Log Creek Mine
Inspection Date:	Tuesday, January 8, 2019	
Areas Inspected:	Underground Areas - unit, secondaries, primaries, belts	
Findings / Law(s) Violated:	No Violations noted.	
Corrective Actions Taken:	None	
Recommendation(s):	None noted	
Inspection Date:	Tuesday, January 22, 2019	
Areas Inspected:	Surface Areas of Underground - office, shop, warehouse, fuel storage areas, parts yard	
Findings / Law(s) Violated:	No Violations noted.	
Corrective Actions Taken:	None	
Recommendation(s):	None noted	
Inspection Date:	Tuesday, February 5, 2019	
Areas Inspected:	Surface Areas of Underground - office, shop, warehouse, fuel storage areas, parts yard	
Findings / Law(s) Violated:	77.1110, 77.410	
Corrective Actions Taken:	Hazards have been addressed with management and corrected	
Recommendation(s):	None noted	
Inspection Date:	Thursday, February 28, 2019	
Areas Inspected:	Underground Areas - unit, secondaries, primaries, belts	
Findings / Law(s) Violated:	75.202	
Corrective Actions Taken:	Hazards have been addressed with management and corrected	
Recommendation(s):	None noted	
Inspection Date:	Friday, March 8, 2019	
Areas Inspected:	Surface Areas of Underground - office, shop, warehouse, fuel storage areas, parts yard	
Findings / Law(s) Violated:	77.1110, 77.1110; 77.410	
Corrective Actions Taken:	Hazards have been addressed with management and corrected	
Recommendation(s):	None noted	
Inspection Date:	Wednesday, March 27, 2019	
Areas Inspected:	Surface Areas of Underground - office, shop, warehouse, fuel storage areas, parts yard	
Findings / Law(s) Violated:	No Violations noted.	

Corrective Actions Taken:	None
Recommendation(s):	None noted